


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

21 - 47 High Street, Feltham, Middlesex, TW13 4UN, UK

 <p>UKAS INSPECTION</p> <p>156</p> <p>Type C Inspection Body</p> <p>Accredited to ISO/IEC 17020:1998</p>	<p>CWE Services Ltd</p> <p>Issue No: 011 Issue date: 04 July 2011</p>	
	<p>The Barn Oak Farm Weston Road Congresbury North Somerset BS49 5EB</p>	<p>Contact: Mr Tracy Lewis Tel: +44 (0)1934 838025/6 Fax: +44 (0)1934 838027 E-Mail: enquiries@cwegroup.co.uk Website: www.cwegroup.co.uk</p>
<p>Inspection performed at/from the above address only</p>		

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures
Surveying for asbestos in premises	<p>Management survey: (domestic, commercial and industrial premises)</p> <p>Refurbishment and demolition survey: (domestic, commercial and industrial premises)</p>	<p>Health and Safety Executive Asbestos: The survey guide (HSG 264, 2010)</p> <p>Documented in-house procedure Asbestos Survey Procedures Manual (ASPM)</p> <p>Documented in-house procedure Asbestos Survey Procedures Manual (ASPM)</p>
	END	