

Schedule of Accreditation

issued by

United Kingdom Accreditation Service

21 - 47 High Street, Feltham, Middlesex, TW13 4UN, UK

 <p>UKAS TESTING 4112</p> <p>Accredited to ISO/IEC 17025:2005</p>	<h3>A W Hainsworth & Sons Ltd</h3>	
	<p>Issue No: 006 Issue date: 13 January 2012</p>	<p>Contact: Mrs Debbie Parnaby/Mr Roy Makepeace Tel: +44 (0)113 257 0391/395 5653 Fax: +44 (0)113 395 5686 E-Mail: debbieparnaby@hainsworth.co.uk/ roymakepeace@hainsworth.co.uk Website: www.hainsworth.co.uk</p>
<p>Spring Valley Mills Stanningley Pudsey West Yorkshire LS28 6DW</p>	<p style="text-align: center;">Testing performed at the above address only</p>	

DETAIL OF ACCREDITATION

Materials/Products tested	Type of test/Properties measured/Range of measurement	Standard specifications/ Equipment/Techniques used
FABRICS	<u>Physical Tests</u>	
	Threads per unit length	BS EN 1049-2:1994 Methods A & B IHM EP001:Jan 2007 based on BS EN 1049-2:1994 Method A
	Determination of width	BS EN 1773:1997
	Abrasion	BS EN ISO 12947:Part 2:1999 BS EN 530:1995 (withdrawn) BS EN 530:2010
	Tensile Strength	BS EN 13934:Part 1:1999
	Weight - Small specimens (Conditioned weight only)	BS EN 12127:1998
	Tear Strength (Trouser)	BS EN ISO 13937-2:2000 BS EN ISO 4674-1 method B:2003
	Tear Strength (Wing Shape)	BS EN ISO 13937-3:2000
	Skew	IHM EP002:Nov 2007 based on BS 2819:1990
	Domestic Washing and Drying Procedures	BS EN ISO 6330:2001 Washing Procedures 1-9A inclusive Drying procedure E only
Preparation, Measuring and Marking	BS EN ISO 3759:2008 (withdrawn) BS EN ISO 3759:2011	
Determination of dimensional change in washing and drying	BS EN ISO 5077:2008	



4112

Accredited to
ISO/IEC 17025:2005

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
21 - 47 High Street, Feltham, Middlesex, TW13 4UN, UK

A W Hainsworth & Sons Ltd
Issue No: 006 Issue date: 13 January 2012

Testing performed at main address only

Materials/Products tested	Type of test/Properties measured/Range of measurement	Standard specifications/ Equipment/Techniques used
FABRICS (cont'd)	<u>Colour Fastness to:</u> Water Sea Water Perspiration Rubbing <u>Dimensional Stability to:</u> Free Steam Water	BS EN ISO 105:E01:1996 (withdrawn) BS EN ISO 105 :E01 :2010 BS EN ISO 105:E02: 1996 (2004) BS EN ISO 105:E04:1996 (withdrawn) BS EN ISO 105:E04:2009 BS EN ISO 105:X12:2002 BS 4323:1979(1995) ISO 3005:1978 BS 4736:1985 ISO 7771:1985
	END	