


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

21 - 47 High Street, Feltham, Middlesex, TW13 4UN, UK

 <p>159</p> <p>Type C Inspection Body</p> <p>Accredited to ISO/IEC 17020:1998</p>	<p>The Environmental Consultancy Ltd trading as RPS Consultants</p> <p>Issue No: 026 Issue date: 20 February 2012</p>	
	<p>14 Cornhill London EC3V 3ND</p>	<p>Contact: Mr S Hurst Tel: +44 (0)20 7280 3200 Fax: +44 (0) 20 7283 9248 E-Mail: hursts@rpsgroup.com Website: www.rpsgroup.com</p>
<p>Inspection performed at/from the locations specified below</p>		

Locations covered by the organisation and their relevant activities

<u>Location details</u>	<u>Activity</u>	<u>Location code</u>
<p>Address RPS Consultants 633-635 Birchwood Boulevard Warrington WA3 7QU</p> <p>Local contact Mr B Durden Tel: +44 (0)1925 849800 Fax: +44 (0)1925 849839 Email: rpswn@rpsgroup.com</p>	<p><u>Asbestos:</u> Surveying</p>	A
<p>Address RPS Consultants 14 Cornhill London EC3V 3ND</p> <p>Local contacts Mr D Blyton Tel: +44 (0)20 7280 3200 Fax: +44 (0) 20 7283 9248 Email: rpslo@rpsgroup.com</p> <p>Mrs C Brown Tel: +44 (0)20 7280 3200 Fax: +44 (0) 20 7283 9248 Email: rpsleg@rpsgroup.com</p>	<p><u>Asbestos:</u> Surveying</p> <p>Legionella: Risk Assessments</p>	B
<p>Address RPS Consultants Noble House Capital Drive Linford Wood Milton Keynes MK14 6QP</p> <p>Local contact Mr B Durden Tel: +44 (0)1235 437100 Fax: +44 (0)1908 669899 Email: rpsmk@rpsgroup.com</p>	<p><u>Asbestos:</u> Surveying</p>	C



159

Type C Inspection Body

Accredited to
ISO/IEC 17020:1998

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
21 - 47 High Street, Feltham, Middlesex, TW13 4UN, UK

The Environmental Consultancy Ltd
trading as
RPS Consultants

Issue No: 026 Issue date: 20 February 2012

Inspection performed by the Organisation at/from the locations specified

<p><u>Address</u> RPS Consultants Tern Place Denmore Road Bridge of Don Aberdeen AB23 8JX</p>	<p><u>Local contact</u> Mr C McLeish Tel: +44 (0)845 60 123 88 Fax: +44 (0)1224 706 998 Email: rpsasb@rpsgroup.com</p>	<p><u>Asbestos:</u> Surveying</p>	<p>D</p>
--	--	---	----------



159

Type C Inspection Body

Accredited to
ISO/IEC 17020:1998

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
21 - 47 High Street, Feltham, Middlesex, TW13 4UN, UK

The Environmental Consultancy Ltd
trading as
RPS Consultants

Issue No: 026 Issue date: 20 February 2012

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for Asbestos in Premises	Management Survey: (domestic, commercial & industrial premises)	Health and Safety Executive Asbestos: The Survey Guide (HSG 264, 2010) Documented In-House procedure RPSCA/2	A, B, C, D
	Refurbishment and demolition survey: (domestic, commercial & industrial premises)	Documented In-House procedure RPSCA/2	
	Priority assessment: (domestic, commercial & industrial premises)	Documented In-House procedure RPSCA/2 (based on requirements included in Health and Safety Executive guides HSG 264 (2010) and HSG 227 (2004))	A, B, C, D
Legionella Risk Assessments	Cooling towers Domestic hot/cold systems Humidifiers and outlets generating a fine spray or aerosol	Documented In-House Method Procedure RPSC L1 based on ACoP L8	B
	Water testing for the purpose of Legionella risk assessment: Temperature	Documented In-House Method Procedure RPSC L1 based on ACoP L8	B
END			