

Schedule of Accreditation
 issued by
United Kingdom Accreditation Service
 21 - 47 High Street, Feltham, Middlesex, TW13 4UN, UK

 175 Type C Inspection Body Accredited to ISO/IEC 17020:1998	Tetra Consulting Ltd	
	Issue No: 007 Issue date: 10 October 2010	
Jessica House Red Lion Square Wandsworth London SW18 4LS	Contact: Mr J Greig Tel: +44 (0)20 8875 0700 Fax: +44 (0)20 8875 0300 E-Mail: James.Greig@tetraconsulting.co.uk Website: www.tetraconsulting.co.uk	
Inspection performed at/from the locations specified below		

Locations covered by the organisation and their relevant activities

Location details	Activity	Location code		
<table style="width: 100%; border: none;"> <tr> <td style="width: 50%; vertical-align: top;"> Address Jessica House Red Lion Square Wandsworth London SW18 4LS </td> <td style="width: 50%; vertical-align: top;"> Local contact Mr J Greig Tel: +44 (0)20 8875 0700 Fax: +44 (0)20 8875 0300 Email: James.Greig@tetraconsulting.co.uk Website: www.tetraconsulting.co.uk </td> </tr> </table>	Address Jessica House Red Lion Square Wandsworth London SW18 4LS	Local contact Mr J Greig Tel: +44 (0)20 8875 0700 Fax: +44 (0)20 8875 0300 Email: James.Greig@tetraconsulting.co.uk Website: www.tetraconsulting.co.uk	Asbestos: Surveying	A
Address Jessica House Red Lion Square Wandsworth London SW18 4LS	Local contact Mr J Greig Tel: +44 (0)20 8875 0700 Fax: +44 (0)20 8875 0300 Email: James.Greig@tetraconsulting.co.uk Website: www.tetraconsulting.co.uk			



175

Type C Inspection Body

Accredited to
ISO/IEC 17020:1998

Schedule of Accreditation
issued by
United Kingdom Accreditation Service

21 - 47 High Street, Feltham, Middlesex, TW13 4UN, UK

Tetra Consulting Ltd

Issue No: 007 Issue date: 10 October 2010

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises	Management survey: (domestic, commercial and industrial premises)	Health and Safety Executive Asbestos: The survey guide (HSG 264, 2010) Documented in-house procedure: Control Manual for UKAS Accredited Procedures Appendix 1	A
	Refurbishment and demolition survey: (domestic, commercial and industrial premises)	Documented in-house procedure: Control Manual for UKAS Accredited Procedures Appendix 1	A
END			