


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

21 - 47 High Street, Feltham, Middlesex, TW13 4UN, UK

 <p>UKAS INSPECTION 235</p> <p>Type C Inspection Body</p> <p>Accredited to ISO/IEC 17020:1998</p>	Resource & Environmental Consultants (Asbestos) Ltd	
	Issue No: 011 Issue date: 08 May 2012	
16 Langlands Place Kelvin South Business Park East Kilbride G75 0YF	Contact: Mr M Holt Tel: +44 (0)1355 574160 Fax: +44 (0)1355 574161 E-Mail: matholt@recltd.co.uk Website: www.recltd.co.uk	
Inspection performed at/from the locations specified below		

Locations covered by the organisation and their relevant activities

Location details	Activity	Location code	
Address 16 Langlands Place Kelvin South Business Park East Kilbride G75 0YF	Local contact Mr David Robertson Tel: +44 (0)1355 574160 Fax: +44 (0)1355 574161 Email: davidr@recltd.co.uk	Asbestos: Surveying	A
Address Osprey House Pacific Quay Broadway Manchester M50 2UE	Local contact: Mr Dave Goodwin Tel: +44 (0)161 868 1300 Fax: +44 (0)161 868 1301 Email: dgoodwin@recltd.co.uk	Asbestos: Surveying	B
Address Unit 19 Kenfig Industrial Estate Margam Port Talbot SA13 2PE	Local contact: Mr Karl Warwick Tel: +44 (0)1656 749823 Fax: +44 (0)1656 740824 Email: kwarwick@recltd.co.uk	Asbestos: Surveying	C
Address Environment House Bullocks Lane Takeley Bishop's Stortford Hertfordshire CM22 6TA	Local contact: Mr Anthony Lacey Tel: +44 (0)1279 879416 Fax: +44 (0)1279 879414 Email: alacey@recltd.co.uk	Asbestos: Surveying	D
Address 69A Killyman St Moy County Tyrone Northern Ireland BT71 7EA	Local contact: Ms Wendy Bryce Tel: +44 (0)28 8778 9180 Fax: +44 (0)28 8778 9171 Email: wbryce@recltd.co.uk	Asbestos: Surveying	E



235

Type C Inspection Body

Accredited to
ISO/IEC 17020:1998

Schedule of Accreditation
issued by
United Kingdom Accreditation Service
21 - 47 High Street, Feltham, Middlesex, TW13 4UN, UK

Resource & Environmental Consultants (Asbestos) Ltd
Issue No: 011 Issue date: 08 May 2012

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises	Management survey: (domestic, commercial and industrial premises)	Health and Safety Executive Asbestos: The survey guide (HSG 264, 2010) Documented in-house procedure REC ASB 03	A, B, C, D, E
	Refurbishment and demolition survey: (domestic, commercial and industrial premises)	Documented in-house procedure REC ASB 03	A, B, C, D, E
	Priority assessment: (domestic, commercial and industrial premises)	Documented in-house procedure REC ASB 03 (based on requirements included in Health and Safety Executive guides HSG 264 (2010) and HSG 227 (2004))	A, B, C, D, E
END			