


# Schedule of Accreditation

issued by

## United Kingdom Accreditation Service

21 - 47 High Street, Feltham, Middlesex, TW13 4UN, UK

 <p><b>UKAS</b> INSPECTION</p> <p><b>4320</b></p> <p><b>Type C</b> <b>Inspection Body</b></p> <p>Accredited to ISO/IEC 17020:1998</p>	<h3 style="margin: 0;">Maylarch Environmental Limited</h3> <p style="margin: 0;"><b>Issue No:</b> 004    <b>Issue date:</b> 24 December 2010</p>	
	<p><b>Oakwood</b> <b>Oakfield Industrial Estate</b> <b>Eynsham</b> <b>Oxfordshire</b> <b>OX29 4TH</b></p>	<p><b>Contact: Mr Simon Ward</b> <b>Tel: +44 (0)1865 883829</b> <b>Fax: +44 (0)1865 881376</b> <b>E-Mail: Simon.Ward@maylarch.co.uk</b> <b>Website: www.maylarch.co.uk</b></p>
<p>Inspection performed at/from the locations specified below</p>		

### Locations covered by the organisation and their relevant activities

Location details	Activity	Location code		
<table style="width: 100%; border: none;"> <tr> <td style="width: 30%;"><b>Address</b> Oakwood Oakfield Industrial Estate Eynsham Oxfordshire OX29 4TH</td> <td style="width: 70%;"><b>Local contact</b> Mr Simon Ward Tel: +44 (0)1865 883829 Fax: +44 (0)1865 881376 E-Mail: Simon.Ward@maylarch.co.uk Website: www.maylarch.co.uk</td> </tr> </table>	<b>Address</b> Oakwood Oakfield Industrial Estate Eynsham Oxfordshire OX29 4TH	<b>Local contact</b> Mr Simon Ward Tel: +44 (0)1865 883829 Fax: +44 (0)1865 881376 E-Mail: Simon.Ward@maylarch.co.uk Website: www.maylarch.co.uk	Asbestos: Surveying	A
<b>Address</b> Oakwood Oakfield Industrial Estate Eynsham Oxfordshire OX29 4TH	<b>Local contact</b> Mr Simon Ward Tel: +44 (0)1865 883829 Fax: +44 (0)1865 881376 E-Mail: Simon.Ward@maylarch.co.uk Website: www.maylarch.co.uk			
<table style="width: 100%; border: none;"> <tr> <td style="width: 30%;"><b>Address</b> Unit K2 Andoversford Link Cheltenham GL54 4LB</td> <td style="width: 70%;"><b>Local contact</b> Mr Simon Ward Tel: +44 (0)1865 883829 Fax: +44 (0)1865 881376 E-Mail: Simon.Ward@maylarch.co.uk Website: www.maylarch.co.uk</td> </tr> </table>	<b>Address</b> Unit K2 Andoversford Link Cheltenham GL54 4LB	<b>Local contact</b> Mr Simon Ward Tel: +44 (0)1865 883829 Fax: +44 (0)1865 881376 E-Mail: Simon.Ward@maylarch.co.uk Website: www.maylarch.co.uk	Asbestos: Surveying	B
<b>Address</b> Unit K2 Andoversford Link Cheltenham GL54 4LB	<b>Local contact</b> Mr Simon Ward Tel: +44 (0)1865 883829 Fax: +44 (0)1865 881376 E-Mail: Simon.Ward@maylarch.co.uk Website: www.maylarch.co.uk			



Type C Inspection Body

Accredited to  
ISO/IEC 17020:1998

**Schedule of Accreditation**  
issued by  
**United Kingdom Accreditation Service**  
21 - 47 High Street, Feltham, Middlesex, TW13 4UN, UK

**Maylarch Environmental Limited**  
**Issue No: 004    Issue date: 24 December 2010**

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for asbestos in premises	Management survey: (domestic, commercial & industrial premises)	Health and Safety Executive Asbestos: The Survey Guide (HSG 264, 2010)  Documented In-House procedure	A, B
	Refurbishment and demolition survey: (domestic, commercial & industrial premises)	Documented In-House procedure	
END			