


Schedule of Accreditation

issued by

United Kingdom Accreditation Service

21 - 47 High Street, Feltham, Middlesex, TW13 4UN, UK

 <p>UKAS INSPECTION 4519</p> <p>Type C Inspection Body</p> <p>Accredited to ISO/IEC 17020:1998</p>	<h3>Core Surveys Limited</h3> <p>Issue No: 001 Issue date: 02 November 2011</p>	
	<p>2 Knights Court Bevernbridge South Chailey East Sussex BN8 4QF</p>	<p>Contact: Mr S Evans Tel: +44 (0)1273 401156 Fax: +44 (0)1273 401121 E-Mail: simon.evans@coresurveys.co.uk Website: www.coresurveys.co.uk</p>
<p>Inspection performed at/from the locations specified below</p>		

Locations covered by the organisation and their relevant activities

Location details	Activity	Location code
<p>Address: 2 Knights Court Bevernbridge South Chailey East Sussex BN8 4QF</p> <p>Local Contact: Mr S Evans Tel: +44 (0)1273 401156 Fax: +44 (0)1273 401121 Email: simon.evans@coresurveys.co.uk</p>	<p><u>Support Functions:</u> Quality Management including document control, auditing and quality control</p> <p><u>Surveying:</u> Asbestos</p>	A
<p>Address: The Studio 13 Lower Castle Street Abergavenny Monmouthshire NP7 5EE</p> <p>Local Contact: Mr V Jones Tel: +44 (0)1873854119 Fax: +44 (0)1273 401121 Email: vaughn@coresurveys.co.uk</p>	<p><u>Support Functions:</u> Quality Management including document control, auditing and quality control</p> <p><u>Surveying:</u> Asbestos</p>	B



4519

Type C Inspection Body

Accredited to
ISO/IEC 17020:1998

Schedule of Accreditation
issued by
United Kingdom Accreditation Service

21 - 47 High Street, Feltham, Middlesex, TW13 4UN, UK

Core Surveys Limited

Issue No: 001 **Issue date:** 02 November 2011

Inspection performed by the Organisation at/from the locations specified

DETAIL OF ACCREDITATION

Field of Inspection	Type and Range of Inspection	Methods and Procedures	Location Code
Surveying for Asbestos in Premises	Management survey: (domestic, commercial and industrial premises) Refurbishment and demolition survey: (domestic, commercial and industrial premises)	Health and Safety Executive Asbestos: The Survey Guide (HSG 264, 2010) Documented In-House Inspection Method CS-MSR-01 Documented In-House Inspection Method CS-RDR-01	A, B
END			